

The following items are required for spray application of WetSuit products. These items are not sold or provided by Neptune Coatings:

COMPRESSOR



17-18 CFM gas driven, 20 gallon portable or 30 gallon stationary air compressor.

PRESSURE WASHER



4 GPM, 3750 PSI with "Turbo Tip"

PAINT SPRAYER



Minimum 2 GPM @3,300 PSI electric,
hydraulic or gas engine driven.
Hose: ½" i.d. x 100' to 150' with 10', 3/8" i.d. whip
Gun: 3,000 – 5,000 PSI working pressure
Gun Tip Size: 427 min. reversible tip

2 GALLON HUDSON SPRAYER



For accelerating cure time for WetSuit 1-Part and WetSuit Trowel.

MOISTURE METER



A gauge used to indicate the degree of moisture down to a depth of 3cm (1.2")

DIAL CALIPER



To measure membrane thickness.

LEAF BLOWER



Min. air speed: 200 MPH

Other Tools & Supplies



Mask or Respirator, used when spraying any WetSuit product. For closed and open air conditions



Paint Brushes & Trowels



A good pair of sharp scissors



Drill with mixing paddle for accelerator



5 gallon pails



Rubber Gloves



Shoe Covers



Spray suits



Rags



Pinesol for pump cleaning



Tarps